ZT0306\_E 0119 Supersedes NEW

Product information presented here reflects conditions at time of publication. Consult factory regarding discrepancies or inconsistencies.



Visit our web site: zoellerpumps.com

# REPLACEMENT PARTS LIST FOR MODELS:


		AUTOMATIC	NONAUTOMATIC
220V	50HZ	WU2702	V2702


### Consult factory for all other models.

#### TO ORDER REPLACEMENT PARTS:

#### PLEASE FURNISH THE FOLLOWING INFORMATION:

- Model number
- Part number of pump
- · Part number and description of part






SINGLE PHASE WIRED-IN FLOAT WIRING DIAGRAM

WIRING DIAGRAM FOR MODELS "V2702"

WIRING DIAGRAM FOR MODELS "WU2702"

## Recommended service part for pump repair

NO.	ITEM	P/N		DESCRIPTION	QTY
1	Cap Repair Kit	094462	1	Power Cord	1
			2	Handle,SS	1
			3	Rubber handke	1
			4	Screw,SS,1/4"-20x1/2L	2
			(5)	Label, SS Nameplate	1
			6	Screw,SS,Ø2.3x5L	4
			7	Cap	1
			8	Seal,O-ring,Ø139.29*3.53	1
2	Impeller Repair Kit	094464	22	Seal, Shaft CERAMIC/Stationary and CARBON/Rotary	2
			23	Spring	1
			24	Seal,O-ring,Ø69.44*3.53	1
			26	Screw,Flat Head Socket,3/16"-24x1/2L	4
			27	Impeller	1
			28	Screw,SS,5/16"x3/4L	4
3	Capacitor Repair Kit	094465	8	Seal,O-ring,Ø139.29*3.53	1
			9	Fixed seat	2
			10	Screw,3/16"x1/4L	2
			1	Capacitor,30uFx450Vac	2
4	Cutter/Shredding Ring Repair Kit	094466	28	Screw,SS,5/16"x3/4L	4
			30	Shredding Ring	1
			<u> </u>	Thick gasket,SS,(@22x@6.5-H7.3)	3
			32	Screw,Flat Head Socket,1/4"x3/4L	4
			33	Cutter, SS	1
			34	Thick gasket, SS, (Ø22xØ6.5-H5)	1



Product information presented here reflects conditions at time of publication. Consult factory regarding discrepancies or inconsistencies.