

Product information presented here reflects conditions at time of publication. Consult factory regarding discrepancies or inconsistencies.

Register your  
 Zoeller Pump Company  
 Product on our website:  
<http://reg.zoellerpumps.com/>




Visit our website:  
[www.zoellerpumps.com](http://www.zoellerpumps.com)

ZT0568\_Eb  
 0122  
 Supersedes  
 New


REPLACEMENT PARTS LIST  
 FOR MODELS:

	AUTOMATIC
220V 50Hz 1PH	V2812
415V 50Hz 3PH	AV2812


Consult factory for all other models.

**TO ORDER REPLACEMENT PARTS:**  
**PLEASE FURNISH THE FOLLOWING INFORMATION:**

- Model number
- Part number of pump
- Part number and description of part




	Color		
SWISS	BLACK	BROWN	BLUE
US standard	WHITE	BLACK	RED
Europe standard	BROWN	BLACK	GREY



# Recommended Service Parts for Pump Repair

NO.	ITEM	P/N	DESCRIPTION		QTY
1	50Hz Impeller Repair Kit	094969	(9)	Screw, SS/5/16"x1"L	8
			(12)	Top L.H. Impeller-50Hz	1
			(20)	Seal, Shaft Silicon Carbide/Stationary & Silicon Carbide Rotary	2
			(35)	Bottom R.H. Impeller-50Hz	1
2	Cutter/ Shredding Ring Repair Kit	094970	(10)	Thick gasket, SS, ( Ø22 x Ø6.5-H5)	1
			(11)	Screw, Flat Head Socket, 1/4"x3/4L	1
			(36)	Cutter, SS	1
			(38)	Shredding Ring	1
			(40)	Screw, SS, 1/4"x1"L	3



**Product information presented here reflects conditions at time of publication. Consult factory regarding discrepancies or inconsistencies.**